

Connet[®] 1 (HI 98305) • *Connet*[®] 2 (HI 98306) • *Connet*[®] 3 (HI 98307)
Conductivity Meters with Automatic Temperature Compensation



Specifications	<i>Connet</i> [®] 1	<i>Connet</i> [®] 2	<i>Connet</i> [®] 3
Range	0 to 1999 µS/cm	0.00 to 19.99 mS/cm	0.00 to 19.99 ppt (g/L)
Resolution	1 µS/cm	0.01 mS/cm	0.01 ppt (g/L)
Accuracy (@20°C/68°F)		±2% F.S.	
Calibration	Manual, 1 point, through slope trimmer		
Temp. Compensation	Automatic, 0 to 50°C, with $\beta=1.9\% \pm 0.15\% / ^\circ\text{C}$, and 25°C (77°F) reference temperature		
Probe (included)	HI 3291	HI 3292	HI 3292
Battery Type / Life	4 x 1.5V alkaline / approx. 150 hours of continuous use		
Environment	0 to 50°C (32 to 122°F); 95% RH max.		
Dimensions / Weight	265 x 29 x 15 mm (10.4 x 1.1 x 0.6") / 400 g (0.88 lb.) complete with the carrying case		

These meters are in compliance with the CE directives

Each meter is supplied in a rugged plastic carrying case with 4-ring conductivity probe, calibration solution bottle (120 mL), screwdriver and instructions.

- Operations:**
- Connect the conductivity probe to the meter (Fig. 1) and turn the unit on by sliding the ON/OFF switch on the top of the instrument.
 - Dip the probe into the solution by ensuring that all 4 rings of the probe are immersed and without exceeding the maximum level (Fig. 2).
 - Stir gently to remove any air bubbles trapped inside the probe and wait for the reading to stabilize.
 - To minimize errors, it is recommended to rinse the probe with some of the sample to be tested before taking measurement.
 - After use, switch the unit off, rinse the probe in alcohol for a few minutes.
 - If the display fades, replace the batteries. Switch the unit off, pull out the battery compartment and replace the batteries (Fig. 3).
 Battery replacement must only take place in a non hazardous area using the battery type specified in this instruction manual.

- Calibration:**
- Dip the probe into the proper (supplied) calibration solution and wait for the reading to stabilize.
 - If necessary, correct the reading to the solution value by slowly turning the calibration trimmer with the supplied screwdriver.

ISTCONMET_05/05




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5



PEWA
 Messtechnik GmbH

Weidenweg 21
 58239 Schwerte

Tel.: 02304-96109-0
 Fax: 02304-96109-88
 E-Mail: info@pewa.de
 Homepage : www.pewa .de