# **INSTRUCTION MANUAL**

HI 96752

# **Calcium and Magnesium High Range** ISM

Thank you for choosing a Hanna product. This manual will provide you with the necessary information for the correct use of the instrument. Please read it carefully before using the meter. If you need additional technical information, do not hesitate to e-mail us at tech@hannainst.com.

# Preliminary examination:

Please examine this product carefully. Make sure that the instrument is not damaged. If any damage occured during shipment, please notify

Each HI 96752 Ion Selective Meter is supplied complete with:


- Two Sample Cuvettes and Caps
- 9V Battery
- Instruction Manual

Note: save all packing material until you are sure that the instrument works correctly. Any defective item must be returned in its original

 $|m{i}|$  For more details about spare parts and accessories see "Accessories".

## **Technical specifications:** Ranae Calcium 0 to 400 mg/l Maanesium 0 to 150 ma/L Resolution 1 ma/L Calcium $\pm 10$ mg/L $\pm 5\%$ of reading at 25°C Accuracy Maanesium $\pm 3$ mg/L $\pm 3\%$ of reading at 25°C Typical EMC Dev. $\pm 1$ mg/L Light Source Light Emitting Diode Silicon Photocell with narrow hand interference Light Detector filter @ 466 nm Method For Calcium: Adaptation of the Oxalate method. For Magnesium: Adaptation of the Calmagite method. 0 to 50°C (32 to 122°F)-Environment max 95% RH non-condensina 1 x 9 volt Battery Type After 10' of non-use in measurement mode: Auto-Shut off after 1 hour of non-use in calibration mode: with last reading reminder. 192 x 104 x 69 mm (7.6 x 4.1 x 2.7") Dimensions 360 g (12.7 oz.).

# Functional description:



- 1. RANGE/GLP/A key: press to change the paramter, press and hold for three seconds to enter GLP mode. In calibration mode press to edit the date and time.
- 2. CAL CHECK key: press to perform the validation of the meter or nress and hold for three seconds to enter calibration made
- 3. ZERO/CFM key: press to zero the meter prior to measurement, to confirm edited values or to confirm factory calibration restore.
- 4. READ/►/TIMER kev: In measurement mode, press to make a measurement, or press and hold for three seconds to start a pre-programmed countdown prior to measurement. In GLP mode press to view the next screen.
- 5. ON/OFF kev: to turn the meter on and off.
- 6. Liquid Crystal Display (LCD)
- 7. Cuvette alianment indicator
- 8. Cuvette holder

# DISPLAY ELEMENTS DESCRIPTION:



- 1. The measuring scheme (lamp, cuvette, detector), appears during different phases of zero or reading measurement
- 2. Error messages and warnings
- 3 The battery icon indicates the charge state of the battery
- 4. The hourglass appears when an internal check is in progress
- 5. Status messages
- 6. The chronometer appears when the reaction timer is running
- 7. The month, day and date icons appear when a date is displayed
- 8. Four digit main display
- 9. Measuring units
- 10. Four digit secondary display

# Errors and warnings:

## ON ZERO READING:



Light High: There is too much light to perform a measurement. Please check the preparation of the zero cuvette.



Light Low: There is not enough light to perform a measurement. Please check the preparation of the zero cuvette.



No Light: The instrument cannot adjust the light level. Please check that the sample does not contain any debris.

# ON SAMPLE READING



Inverted cuvettes: The sample and the zero cuvette are inverted.



Zero: A zero reading was not taken. Follow the instructions of the measurement procedure for zeroing the meter.



Under range: A blinking "0" indicates that the sample absorbs less light than the zero reference. Check the procedure and make sure you use the same cuvette for reference (zero) and measurement



Over Range: A flashing value of the maximum concentration indicates an over range condition. The concentration of the sample is beyond the programmed range: dilute the sample and re-run the test.

# DURING CALIBRATION PROCEDURE:



Standard Low: The standard reading is less than expected.



Standard High: The standard reading is higher than expected.

# OTHER ERRORS AND WARNINGS:



Cap error: Appears when external light enters in the analysis cell. Assure that the cuvette can is present.



Cooling lamp: The instrument waits for the lamp to cool down.



dEAd

**BALL** 

Battery low: The battery must be replaced

Dead battery: This indicates that the battery is dead and must be replaced. Once this indication is displayed, normal operation of the instrument will be interrupted. Change the battery and restart the meter.

displays dashes and "P1" (Calcium) and

"P2" (Magnesium) the meter is ready. The

code that appears on the secondary display is

the one of the last selected parameter. If

necessary press RANGE/GLP/A to change

# Measurement procedure:

Measurement ▼

2

3

1 mL

4

<**●** P2

- 0.0 -

8-9 1 mL 5 9277528 Ca

P2

0.5 mL of sample





- and invert several times to mix. 4. Place the cuvette into the holder and ensure that the notch on the cap is positioned securely into the groove.
- Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display, depending on the measurement phase.
- 6. After a few seconds the display will show "-0.0-". The meter is now zeroed and rendy for measurement
- 7. Remove the cuvette
- Calcium: Using a 1 mL syringe add exactly 1 mL of the HI 93752B-0 Ca Oxalate reagent. Magnesium: Using another 1 mL syringe. add to the cuvette exactly 0.5 mL of sample. Note: Do not mix up the two 1 mL syringes!
- 9. Calcium: Replace the cap and invert the cuvette 10 times to mix. Magnesium: Replace the cap and invert
- several times to mix. 10 • Replace the cuvette into the holder and ensure that the notch on the cap is
- positioned securely into the groove. 11 • Press READ/►/TIMER for three seconds The display will show the countdown prior to measurement. The beeper is playing a beep at the end of countdown period.

Calcium only: invert again the cuvette 10 times replace the cuvette and press READ/ ►/TIMER.



Messtechnik GmbH

Weidenweg 21 58239 Schwerte

Tel.: 02304-96109-0 Fax: 02304-96109-88 E-Mail: info@pewa.de Homepage: www.pewa.de

Alternatively wait for: Calcium: 5' minutes, then invert again the cuvette 10 times Magnesium:Wait for 15 seconds 12 then press RFAD/>/TIMFR In all cases the lamp, cuvette and

detector icons will appear on the display.

depending on the measurement phase.



65

Validation **▼** 

< P |

- 0.0 -

P1

12. The instrument directly displays concentration in ma/L of Calcium or Magnesium on the LCD, depending on the selected parameter.


# INTERFERENCES:

<ul> <li><u>Calcium</u>:</li> </ul>	Concentration	Reading
Acidity (as CaCO <sub>3</sub> )	above 1000 mg/L	lower
Alkalinity (as CaCO <sub>2</sub> )	above 1000 mg/L	higher
Magnesium (Mg <sup>2+</sup> )	above 400 mg/L	higher
<ul> <li>Magnesium:</li> </ul>	Concentration	Reading
Acidity (as CaCO <sub>3</sub> ) Alkalinity (as CaCO <sub>3</sub> ) Calcium (Ca <sup>2+</sup> )	above 1000 mg/L	lower
Alkalinity (as CaCO <sub>3</sub> )	above 1000 mg/L	higher
Calcium (Ca <sup>2+</sup> )	above 200 mg/L	higher
Iron	-	higher
Aluminum	-	higher
Copper	-	higher

# Validation and Calibration procedures

Warning: do not validate or calibrate the instrument with standard solutions other than the Hanna CAL CHECK™ Standards, otherwise erroneous results will be obtained.

For accurate validation and calibration results, please perform tests at room temperature (18 to 25°C: 64.5 to 77.0°F).



# VAI IDATION

Note: The validation is performed only for the selected parameter. For full validation of the instrument, the following procedure must be performed for each parameter.

- 1 Turn the meter on by pressing ON/OFF. 3
- 2. When the beeper sounds briefly and the LCD displays dashes, the meter is ready.
- 3 Place the CAL CHECK™ Standard Cuvette A into the cuvette holder and ensure that the notch on the cap is positioned securely into the groove.
- 4. Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display, depending on the measurement phase.
- 5. After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for validation.
- 6. Remove the cuvette.
- 7. Place the specific CAL CHECK<sup>TM</sup> Standard Cuvette B into the cuvette holder for: Calcium: B. HI 96752-11 Magnesium: B. HI 96754-11 Ensure that the notch on the cap is positioned securely into the groove.



9. At the end of the measurement the display will show the validation standard value The reading should be within specifications as reported on the CAL CHECK™ Standard Certificate. If the value is found out of specifications, please check that the cuvettes are free of fingerprints, oil or dirt and repeat validation. If results are still found out of specifications then recalibrate the instrument.



é• P !





**Calibration ▼** 

60 P1

200.

P1

# CALIBRATION

- Note: It is possible to interrupt the calibration procedure at any time by pressing CAL CHECK or ON/OFF keys. When calibrating, only the selected range is affected.
- 1 Turn the meter on by pressing ON/OFF.
- 2. When the beener sounds briefly and the LCD displays dashes, the meter is ready.
- **3•** To change the range, simply press **5** RANGF/GI P/▲
- 4. Press and hold CAL CHECK for three seconds to enter calibration mode. The display will show "CAL" during calibration procedure. The blinking "ZERO" asks for instrument zeroing. 6-7
- 5 Place the CAL CHECK™ Standard Cuvette A into the cuvette holder and ensure that the notch on the cap is positioned securely into the groove.
- 6. Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display. depending on the measurement phase.
- 7. After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for calibration. The blinking "READ" asks for reading calibration standard.
- 8. Remove the cuvette.
- 9. Place the specific CAL CHECK<sup>TM</sup> Standard Cuvette B into the cuvette holder, for: Calcium: B, HI 96752-11 Magnesium: B, HI 96754-11 Ensure that the notch on the cap is positioned 10-11 securely into the groove.
- **10** Press **READ/►/TIMER** and the lamp, cuvette and detector icons will appear on the display, depending on the measurement
- 11 The instrument will show for three seconds the CAL CHECK™ standard value.



Note: If the display shows "STD HIGH", the

- 12 Then the date of last calibration (e.a.: "01.08.2009") appears on the display, or "01.01.2009" if the factory calibration was selected before. In both cases the year number is blinking, ready for date input.
- 13 Press RANGE/GLP/▲ to edit the desired vear (2009-2099). If the key is kept pressed. the year number is automatically increased.
- 14 When the correct year has been set, press ZERO/CFM or READ/>/TIMER to confirm. Now the display will show the month blinking.
- 15 Press RANGE/GLP/▲ to edit the desired month (01-12) If the key is kent pressed the month number is automatically increased. 16 • When the correct month has been set, press
- ZERO/CFM or READ/►/TIMER to confirm. Now the display will show the day blinking. 17 • Press RANGE/GLP/▲ to edit the desired
- day (01-31). If the key is kept pressed, the day number is automatically increased. Note: It is possible to change the editing from day to year and to month by pressing RFAD/►/TIMER
- 18 Press 7FRO/CFM to save the calibration date 19 • The instrument displays "Stor" for one
- second and the calibration is saved. 20 • The instrument will return automatically to measurement mode by displaying dashes on the LCD.

In GLP mode, the last calibration date can be verified and the factory calibration can be restored.

Stor

P I

0" 10"81

0 108

15-16

2009

eöös`

≥≥000≤

# LAST CALIBRATION DATE

- 1 Press and hold RANGE/GLP/A for three seconds to enter GLP mode. The calibration month and day will appear on the main display and the year on the secondary display.
- 2. If no calibration was performed, the factory calibration message, "F.CAL" will appear on the main display and the instrument returns to measurement mode after three seconds.








## FACTORY CALIBRATION RESTORE

It is possible to delete the calibration and restore factory calibration.





calibration or press RANGE/GLP/A again to abort factory calibration restore.

Factory Calibration



3 • Press ZERO/CFM to restore the factory 3-4

4. The instrument briefly indicates "donE" upon restoration of factory calibration prior to returning to measurement mode.

Battery management

# Restore **▼**



HI 721310 9V battery (10 pcs.) HI 731318 Cloth for wiping cuvettes (4 pcs.)

HI 731331 HI 731335 Caps for cuvettes

HI 93703-50 Cuvette cleaning solution (230 mL)

donE

65

To save the battery, the instrument shuts down after 10 minutes of non-use in measurement mode and after 1 hour of non-use in calibration

If a valid measurement was displayed before auto-shut off, the value is displayed when the instrument is switched on. The blinking "ZERO" means that a new zero has to be performed.



One fresh battery lasts for arround 750 measurements, depending on the

The remaining battery capacity is evaluated at the instrument startup and after each measurement.

The instrument displays a battery indicator with three levels as follows:

- 3 lines for 100 % capacity
- . 2 lines for 66 % capacity
- 1 line for 33 % capacity
- · Battery icon blinking if the capacity is under 10 %.

If the battery is empty and accurate measurements can't be taken any more, the instrument shows "dEAd bAtt" and turns off.

To restart the instrument, the battery must be replaced with a fresh one. To replace the instrument's battery, follow the steps:

- Turn the instrument off by pressing ON/OFF.
- · Turn the instrument upside down and remove the battery cover by turning it counterclockwise.



- · Extract the battery from its location and replace it with a fresh one.
- Insert back the battery cover and turn it clockwise to close.

# Accessories

# REAGENT SETS

HI 93752-01 Reagents for 100 tests (50 tests Ca and 50 tests Ma) HI 93752-03 Reggents for 300 tests (150 tests Cg and 150 tests Mg)

# OTHER ACCESSORIES

HI 96752-11 CAL CHECK™ Standard Cuvettes for Calcium(1 set) HI 96754-11 CAL CHECK™ Standard Cuvettes for Magnesium(1 set)

Glass cuvettes (4 pcs.)

# Warrantv

HI 96752 is warranted for two years against defects in workmanship and materials when used for its intended purpose and maintained according to the instructions

This warranty is limited to repair or replacement free of charge.

Damages due to accident, misuse, tampering or lack of prescribed maintenance are not covered

If service is required, contact your dealer. If under warranty, report the model number, date of purchase, serial number and the nature of the failure. If the repair is not covered by the warranty, you will be notified of the charges incurred

If the instrument is to be returned to Hanna Instruments, first obtain a Returned Goods Authorization Number from the Customer Service Department and then send it with shipment costs prepaid. When shipping any instrument, make sure it is properly packaged for complete protection.

To validate your warranty, fill out and return the enclosed warranty card within 14 days from the date of purchase.

# Recommendations for Users

Before using these products, make sure that they are entirely suitable for your specific application and for the environment in which they are used.

Operation of these instruments may cause unacceptable interferences to other electronic equipments, this requiring the operator to take all peressary steps to correct interferences

Any variation introduced by the user to the supplied equipment may degrade the instrument's EMC

To avoid damages or burns, do not out the instrument in microwave oven. For yours and the instrument safety do not use or store the instrument in hazardous environment

Hanna Instruments reserves the right to modify the design, construction and appearance of its products without advance notice.

For additional information, contact your dealer or the nearest

Hanna Customer Service Center. To find the Hanna Office in your area. visit our web site