

PEWA Messtechnik GmbH

Weidenweg 21 58239 Schwerte

Tel.: 02304-96109-0 Fax: 02304-96109-88 E-Mail: info@pewa.de Homepage : www.pewa .de

SPECIFICATIONS   Range / Resolution   DiST®1 (H198300/301) 19   DiST®2 (H198302) 10.0   DiST®3 (H198303) 1999   DiST®4 (H198304) 19.99   Accuracy (@20°C/68°F) 19	00 ppt / 0.01ppt p µS/cm / 1µS/cm mS/cm / 0.01mS/cm ±2% f.s.	
Typical EMC Deviation $\pm$ 1% f.s.		
TDS Factor HI 98300 HI 98301 / HI 98302	0.65 0.5	
Calibration Solutions		
HI 98300 HI 7	<b>'0442</b> (1500 ppm)	
	<b>'0032</b> (1382 ppm)	
	<b>70038</b> (6.44 ppt)	
HI 98303 HI 70	<b>031</b> (1413 µS/cm)	
	<b>139</b> (5.00 mS/cm) or	
	<b>030</b> (12.88 mS/cm)	
Temperature Compensation		
	to 50°C (32 to 122°F)	
	50°C (32 to 122°F);	
	5% non-condensing	
Battery Type 4	x 1.5V alkaline	
Battery Life approx	x. 200 hours of use	
Dimensions 17	5 x 41 x 23 mm	
(6	.9 x 1.6 x 0.9")	
Weight	95 g (3.4 oz.)	

#### WARRANTY

These meters are guaranteed for one year against defects in workmanship and materials when used for their intended purpose and maintained according to instructions. Probes are guaranteed for six months. This warranty is limited to repair or replacement free of charge. Damages due to accident, misuse, tampering or lack of prescribed maintenance are not covered. If service is required, contact the dealer from whom you purchased the instrument. If under warranty, report the model number, date of purchase, serial number and the nature of the failure. If the repair is not covered by the warranty, you will be notified of the charges incurred. If the instrument is to be returned to Hanna Instruments, first obtain a Returned Goods Authorization Number from the Customer Service department and then send it with shipment costs prepaid. When shipping any instrument, make sure it is properly packaged for complete protection.

## The $\text{DiST}^{\circledast}$ models are in compliance with the CE directives.

ISTDISTNEW-R5 05/05

# DiST®

HI 98300 / 301 / 302 HI 98303 / 304

EC and TDS Testers with ATC





#### **OPERATION**

• Remove the protective cap, turn the DiST® on, and immerse it into the solution to be tested, without exceeding the maximum immersion level.

N

- Stir gently and wait for the reading to stabilize. DiST<sup>®</sup> automatically compensates for temperature variations.
- The reading on display is directly expressed in: ppm (mg/L) for DiST®1 (HI 98300 / 301), ppt (g/L) for DiST®2 (HI 98302), µS/cm for DiST®3 (HI 98303) and mS/cm for DiST®4 (HI 98304).

#### CALIBRATION

- Immerse the DiST<sup>®</sup> in the proper calibration solution (see Specifications table), without exceeding the maximum immersion level.
- Allow the reading to stabilize and with a small screwdriver adjust the calibration trimmer until the display shows the required solution value.

For example **HI 70032** is the correct calibration solution for **HI 98301**, and the trimmer should be turned until the display shows "1382".



#### **PROBE REPLACEMENT**


For replacing the probe, contact your Dealer or the nearest Hanna Service Center.

- Replace the built-in probe with a new:
  - HI 73301 for DiST®1
  - HI 73302 for DiST®2
  - HI 73303 for DiST®3
  - HI 73304 for DiST®4

#### BEPS AND BATTERY REPLACEMENT

DiS<sup>®</sup>T is provided with BEPS (Battery Error Preventing System), which avoids any erroneous reading due to low battery level, by switching the meter off.

To replace the batteries, slide off the battery compartment cover and replace all four 1.5V batteries while paying attention to their polarity.



Batteries should only be replaced in a nonhazardous area, and using the battery type specified in this instruction manual.

### ACCESSORIES

HI 70030P	12880 $\mu$ S/cm calibration solution, 20 mL sachet, 25 pcs
HI 70031P	1413 $\mu$ S/cm calibration solution, 20 mL sachet, 25 pcs
HI 70032P	1382 ppm (mg/L) calibration so- lution, 20 mL sachet, 25 pcs
HI 70038P	6.44 ppt (g/L) calibration solu- tion, 20 mL sachet, 25 pcs
HI 70039P	5000 $\mu$ S/cm calibration solution, 20 mL sachet, 25 pcs
HI 70442P	1500 ppm calibration solution, 20 mL sachet, 25 pcs
HI 73301	Spare electrode for DiST®1
HI 73302	Spare electrode for DiST®2
HI 73303	Spare electrode for DiST®3
HI 73304	Spare electrode for DiST®4
HI 731326	Calibration screwdriver (20 pcs.)

**DIST** is a registered Trademark of Hanna Instruments