ORDERING INFORMATION	
ltem (Qty)	Cat. No.
Battery Ground-Fault Locator	
120 volt, 60 Hz	835140
240 volt, 50 Hz	835140-1
220 volt, 60 Hz	835140-2
120 volt, 50 Hz	835140-3
Included Accessories	
Clamp-on current sensor, 33 ft (10 m), 2 in. (50 mm) opening –	
maximum dc current: 20 A [1]	835142
Fault simulator [1]	835145
Output lead extension, 14.9 ft (4.5 m) [1]	835144
Output lead, 6.6 ft (2 m) [1]	835143
Power cord, ac	17032
Instruction manual [1]	AVTM835140
Optional Accessories	
Mini clamp-on current sensor, 0.5 in. (127 mm) opening – maximum dc current: 5 A	835146
Busbar clamp-on sensor, 2 x 4 in. (50 x 101 mm) opening – maximum dc current: 50 A	835147



PEWA Messtechnik GmbH

Weidenweg 21 58239 Schwerte

Tel.: 02304-96109-0 Fax: 02304-96109-88 E-Mail: info@pewa.de Homepage : www.pewa .de