

ORDERING INFORMATION

Item (Qty)	Cat. No.
Transformer Ohmmeter 120/240 volt, 50/60 Hz input	MTO210
Included Accessories	
V1 Potential Lead Set, 60 ft (18 m)	2000-700
V2 Potential Lead Set, 60 ft (18 m)	2000-701
Current Lead Set, 60 ft (18 m)	2000-702
Jumper Lead, 30 ft (9 m)	2000-703
Ground Lead, 15 ft (4.5 m)	4702-7
RS232 Cable for connecting to a PC and Printer	CA-RS232
Remote Hand Switch	30915-220
AC Power Cord (IEC60320-C13 to US standard)	17032
AC Power Cord (IEC60320-C13 to Schuko CEE 7/7)	17032-13
Quick Start Guide	37178
Canvas Carrying Bag (for leadset)	30915-211
CAT5e Patch Cable	36798
Instruction Manual	ATVMMTO210
PowerDB LITE	

Item (Qty)	Cat. No.
Optional Accessories	
V1 Potential Lead Set, 100 ft (30 m)	2001-403
V2 Potential Lead Set, 100 ft (30 m)	2001-404
Jumper Lead, 50 ft (15 m)	2001-405
Current Lead Set, 100 ft (30 m)	2001-406
Kelvin Lead Set, 60 ft (18 m)	2001-407
Kelvin Lead Set, 100 ft (30 m)	2001-408
Test Lead Set, 60 ft (18 m) including V1, V2, Current and 30 ft (9 m) Jumper Lead	1001-425
Test Lead Set, 100 ft (30 m) including V1, V2, Current and 50 ft Jumper Lead	1001-451
Beacon Strobe Light	37181
Printer (includes battery/line powered serial thermal printer) 120 V, 60 Hz	1001-390
230 V, 50 Hz	1001-401
Foam-lined Transit Case	37009
USB to Ethernet Adapter	90001-541
PowerDB (full version) Software, 1st machine license, soft key	DB1001
PowerDB (full version) Software, 1st machine license, USB dongle	DB1001S



PEWA
Messtechnik GmbH
Weidenweg 21
58239 Schwerte

Tel.: 02304-96109-0
Fax: 02304-96109-88
E-Mail: info@pewa.de
Homepage: www.pewa.de