

## Arbitrary/Function Generators

▶ AFG3011 • AFG3021B • AFG3022B • AFG3101 • AFG3102 • AFG3251 • AFG3252

### ▶ Ordering Information

#### **AFG3011, AFG3021B, AFG3022B, AFG3101, AFG3102, AFG3251, AFG3252**

Arbitrary/Function Generator.

**Includes:** Quick-start user manual, power cord, USB cable, CD-ROM with programmer manual, service manual, LabView and IVI drivers, CD-ROM with ArbExpress® software, NIST-traceable calibration certificate. Please specify power plug when ordering.

#### **International Power Plugs**

- Opt. A0 – North America power.
- Opt. A1 – Universal EURO power.
- Opt. A2 – United Kingdom power.
- Opt. A3 – Australia power.
- Opt. A5 – Switzerland power.
- Opt. A6 – Japan power.
- Opt. A10 – China power.
- Opt. A11 – India power.
- Opt. A99 – No power cord or AC adapter.

#### **Manual Options**

Note: Includes front panel overlay.

- Opt. L0 – English (071-1631-xx).
- Opt. L1 – French (071-1632-xx).
- Opt. L2 – Italian (071-1669-xx).
- Opt. L3 – German (071-1633-xx).
- Opt. L4 – Spanish (071-1670-xx).
- Opt. L5 – Japanese (071-1634-xx).
- Opt. L7 – Simple Chinese (071-1635-xx).
- Opt. L8 – Traditional Chinese (071-1636-xx).
- Opt. L9 – Korean (071-1637-xx).
- Opt. L10 – Russian (071-1638-xx).
- Opt. L99 – No manual.

#### **Service**

- Opt. C3 – Calibration Service 3 Years.
- Opt. C5 – Calibration Service 5 Years.
- Opt. CA1 – Single calibration event or coverage for the designated calibration interval, whichever comes first.
- Opt. D1 – Calibration Data Report.
- Opt. D3 – Calibration Data Report 3 Years (with Option C3).
- Opt. D5 – Calibration Data Report 5 Years (with Option C5).
- Opt. R5 – Repair Service 5 Years.

#### **Warranty**

Three year warranty on parts and labor.

#### **Recommended Accessories**

- Rackmount Kit – RM3100.
- Fuse adapter, BNC-P to BNC-R. – 013-0345-00.
- Fuse set, 3 pcs, 0.125 A. – 159-0454-00.
- BNC cable shielded, 3 ft. – 012-0482-00.
- BNC cable shielded, 9 ft. – 012-1256-00.
- GPIB cable, double shielded – 012-0991-00.



▶ BNC Fuse Adapter and 0.125 A Fuse.



**PEWA**  
Messtechnik GmbH

Weidenweg 21  
58239 Schwerte

Tel.: 02304-96109-0  
Fax: 02304-96109-88  
E-Mail: [info@pewa.de](mailto:info@pewa.de)  
Homepage : [www.pewa.de](http://www.pewa.de)