



HI 768A

Pt100 Probes for Air & Gas

Click to Buy



PEWA
Messtechnik GmbH
Weidenweg 21
58239 Schwerte

Tel.: 02304-96109-0
Fax: 02304-96109-88
E-Mail: Info@pewa.de
Homepage: www.pewa.de

Pt100 probe for measuring the temperature of air and gases

Specifications

Range	-30 to 350°C (-22 to 622°F)
Sensor	Pt100
Accuracy	±0.25°C (±0.5°F) ±3% of reading
Probe Handle	Carilon®
Interchange Error	±0.2°C (±0.4°F)
Probe	stainless steel AISI 316
Response Time	30 seconds
Cable Length	1 m (3.3')