



**PEWA**  
Messtechnik GmbH  
Weidenweg 21  
58239 Schwerte  
Tel.: 02304-96109-0  
Fax: 02304-96109-88  
E-Mail: info@pewa.de  
Homepage : www.pewa .de

**ORDERING INFORMATION**

<b>Item (Qty)</b>	<b>Cat. No.</b>	<b>Item</b>	<b>Cat. No.</b>
Model CB-100			
120 V, 60 Hz	810130	<b>Optional Accessories</b>	
240 V, 50 Hz	810130-1	Range extension adapter	
220 V, 60 Hz	810130-2	For 120 volt, 60 Hz operation	810132
Model CB-100 for 120 V, 60 Hz complete with range extension adapter	810130-3	For 240 volt, 50 Hz operation	810132-1
Model CB-100 for 240 V, 50 Hz complete with range extension adapter	810130-4	Lead sets	
Model CB-100 for 220 V, 60 Hz complete with range extension adapter	810130-5	3.3 ft (1 m)	810136-2
		59.4 ft (18 m)	810136-3
<b>Included Accessories</b>			
Lead set, 33 ft (10 m)	810136		
Line cord, ac	17032		
Transport case	MC803		
CB-CHEK Calibrator	810133		
Instruction manual	AVTM810130		