## **DLRO test leads fitted with duplex Connectors**

DLRO test leads

# DLRO test leads fitted with duplex Connectors DLRO test leads



- Carry one lead set and swap terminations
- Simple push and twist for a quick change
- Lockable twist cap secures the leads
- Four terminal 10 A test lead system
- Warning / Indicator lights for DLRO10 range
- Extension leads available

#### **DESCRIPTION**

Duplex connect test lead system for use with any Megger 10 A DLRO and BT51 instruments

The Megger DLRO duplex connect four terminal test lead system is designed to provide the most cost effective and convenient way to provide the user with all of the test lead terminations and lead lengths required for the many different applications encountered in low resistance testing.



At the center of this unique test lead system is a bespoke connector allowing terminations such as kelvin clips or duplex test probes to be changed as required. There are two connector versions, one being fitted with indicator LEDs that operate with the DLRO10 range of instruments. The indicator LEDs provide enhanced safety and convenience with indications as follows:

#### **DLRO10 and DLRO10HD**

- Warning of connection to hazardous live voltage
- When continuity is made
- When a test complete and measurement is on instrument display

#### DLRO10X adds

■ Indication of pass / fail to user set test limits

All of these important indications are therefore seen near the point of connection without needing to view the instrument display. There is even a 6 m extension lead to provide the ultimate in flexibility.

## **SAFETY WARNINGS**

These safety warnings must be read and understood before the instrument is used.

Always refer to the user manual of the instrument being used with these test leads.

Do not touch the universal connector during test or while connected to hazardous voltages.

Whenever possible, circuits should be de-energized before testing.

If it is impossible to de-energize the circuit, (e.g. high voltage batteries cannot be switched off while their connections are tested) the user must be aware of the dangers. The instrument terminals will become live when connected to the circuit. Therefore when used on hazardous voltages the Megger terminal cover (available separately) must be used. See the accessories section of this user quide.

When running any test, or when attached to a test load, do not undo the modular connections. Isolate both test leads before changing any part of the modular leadset.

## Megger. DLRO test leads fitted with duplex Connectors

DLRO test leads

These test leads on their own are not safety CAT rated due to the bare hook terminations. However when fitted with insulating instrument terminal covers and a suitably rated test termination the overall safety CAT rating will be the lowest of the ratings between the instrument, the terminal covers and the test termination.

For example if used with a DLRO10HD fitted with terminal cover part number 1002-390 and a pair of DP1-C duplex probes the safety rating of the complete system will be CATIII 300 V. However if the test terminations were changed to KC1-C Kelvin clips the safety rating would drop to <30 V as the KC1-C are un-rated.

## Testing inductive circuits can be hazardous:

- After testing an inductive load there will be an amount of energy stored in the inductance. This energy is released in the form of a discharge current. Disconnecting an inductive load while current is still flowing will cause a high voltage arc, which is a danger to both the user and the item under test
- The DLRO connector lit lead sets are fitted with a 'test in progress lamp' associated with the TEST button which indicates that current is flowing in the C1-C2 loop. For testing large inductive resistances the current carrying leads should be connected securely to the item under test before starting the test
- It is not recommended that duplex handspikes be used to carry out tests on inductive loads. If inadvertently using the handspikes on an inductive load, the L1 lamp on the handspikes will flash amber while discharge current flows, thereby duplicating the function of the 'I' lamp on the instrument. It is important to maintain contact until the L1 light stops flashing amber and turns green indicating the end of the test

This product is not intrinsically safe. Do not use in an explosive atmosphere.

Do not operate the test leads or connect to any external system if any visible signs of damage are apparent or if they have been stored for prolonged periods in unfavourable conditions.

## Inspection

Before each use of the test leads, perform a thorough visual inspection to confirm that their condition is good, with no damaged or broken insulation.

The Measurement Category rating of the measurement system is that of the lowest rated component. If any part of the measurement leads is unrated, the instrument is safe for connection only up to 30 V.

# APPLICATION DUPLEX CONNECT SYSTEM – COMPONENT PARTS



## **CONNECT TEST LEADS WITH INDICATOR LIGHTS**

These duplex test leads are single test leads supplied without terminations.

	Test Lead (1 supplied)	Order part number:
TL1.5-CL	1.5 m connect lit	1006-456
TL3-CL	3 m connect lit	1006-458
TL6-CL	6 m connect lit	1006-459

Lead resistances - C hook termination to connector

1.5m lead (1 off) 20m ohm 3m leads (1 off) 30m ohm 6m leads (1 off) 40m ohm

## Description

These duplex test leads are fitted with hook terminations for connecting to an instrument and a connector plug equipped with ultra-bright LED indicator lights viewable from any direction.

Test connection terminations are supplied separately.

The duplex connector incorporates a locking ring to prevent test connections being pulled off in use.

Indicator lights operate with DLRO10, DLRO10X and DLRO10HD via third connection plug. The function of these indicator lights are listed at the beginning of this document in the introduction.

## These leads are designed to fit:

- DLRO10
- DLRO10X
- DLRO10HD

## **DLRO test leads fitted with duplex Connectors**

DLRO test leads

# CONNECT TEST LEADS WITHOUT INDICATOR LIGHTS



These duplex test leads are single test leads supplied without terminations.

	Test Lead (1 supplied)	Order part number:
TL1.5-C	1.5m connect	1006-452
TL3-C	3m connect	1006-454
TL6-C	6m connect	1006-455

Lead resistances - C hook termination to connector

1.5m lead (1 off) 20m ohm 3m leads (1 off) 30m ohm

6m leads (1 off) 40m ohm

## Description

These duplex test leads are fitted with hook terminations for connecting to an instrument and a Connex plug.

Test connection terminations are supplied separately.

The duplex connector incorporates a locking ring to prevent test connections being pulled off in use.

## These leads are designed to fit:

- DLRO10
- DLRO10X
- DLRO10HD

# There are separate versions available to fit the BT51 as follows:

	Test Lead (1 supplied)	Order part number:
TL3-C-BT51	3m connect for BT51	1007-023
TL6-C-BT51	6m connect for BT51	1007-024

## **CONNECT EXTENSION LEAD**



EL6-C Extension Lead

6 m connect (1 supplied) 1006-460

Lead resistance 40m ohm

## Description

This 6 m long duplex connect extension lead is designed to extend the duplex connect test leads that are without indicator lights.

More than one extension lead can be used to create even longer test lead lengths. However the overall lead resistance must be taken into account. The higher the overall loop resistance, including the test piece, the lower the maximum test current available will be.

Any 10 A DLRO instrument fitted with a pair of 3 m test leads and any test lead terminations (duplex probes or kelvin clips) can have up to 2 x 6 m extension leads used and still be able to supply 10 A test current. This is because the overall resistance of this combination is below the 100 m ohm lead resistance maximum specified.

# These extension leads are designed to fit any of these test leads:

- TL1.5-C
- TL3-C
- TL3-C-BT51
- TL6-C
- TL6-C-BT51

Note: These extension leads will not fit any of the leads fitted with indicator lights

## **DLRO test leads fitted with duplex Connectors**

DLRO test leads

## Megger.

# LEAD TEST CONNECTION TERMINATIONS AVAILABLE – SOLD INDIVIDUALLY

#### **DUPLEX CONNECT PROBE**



DP1-C

Duplex Probe 1 - connect Order part number: 1006-450

## Description

Duplex connect handspike with sprung loaded tips fitted with a connector socket for easy connection to any connector test lead. Replaceable probe tips have hardened needle points, gold plated for excellent low resistance contact. Tips are sprung to provide 1.3 kg of force using stainless steel springs.

Ideal for general applications where a good reliable connection is required on none coated or corroded surfaces. To further limit the possibility of damage to test piece waffle tip, sometimes referred to a serrated tips are available as an option.

Maximum current rating 10 A
Connector to probe tip resistance

14m ohm

Probe spacing between P and C tips:

6 mm

Will fit Any duplex connect test lead and

extension lead

**Safety** CAT III 600 V only when suitable

terminal covers are used

Spare / optional parts Order part number:

Replacement needle tips 2003-551 Waffle / serrated tips 25940-014

## **DUPLEX CONNECT TWIST PROBE**



DTP1-C

Duplex Twist Probe 1 - Connect Order part number: 1006-449

#### Description

Duplex connect handspike with sprung twisting tips fitted with a connector socket for easy connection to any connect test lead.

As the probe is pressed onto the test piece the tips compress and twist at the same time providing 2.4 kg of spring force. Probe tips are hardened and tempered before four equal-spaced flats are ground to provide a square shape tip, making these probes ideal for cutting through surface coatings or corrosion on test piece for a good contact.

To assist reliability the probes internal electrical connections are assisted by using an innovative volute spring eliminating the need for a separate current carrying brad.

**Maximum current rating** 10 A

Connector to probe tip resistance

14m ohm

Probe spacing between P and C tips:

10 mm

Will fit Any Duplex Connex test lead and

extension lead

Safety <30 V only

## **DLRO test leads fitted with duplex Connectors**

DLRO test leads

## **CONCENTRIC DUPLEX CONNECT PROBE**



CP1-C

Concentric Probe 1 - connect Order part number: 1006-448

## Description

Duplex connect concentric handspike with sprung loaded potential tip fitted with a connector socket for easy connection to any connector test lead.

The C connection is made via an outer hardened and tempered steel crown with two contact points or tips.

The replaceable central potential probe tip has a hardened needle point, gold plated for excellent low resistance contact. The P tip is sprung to provide 1.3kg of force and uses a stainless steel spring. Ideal for general applications where a good reliable connection is required on none coated or corroded surfaces. The long probe length and small diameter makes this probe ideal for reaching deeply recessed terminal screws. There are also applications where connection to rivet heads or screw/bolt heads are required. To further limit the possibility of damage to test piece waffle tip, sometimes referred to a serrated tip is available as an option.

Maximum current rating 10 A

Connector to probe tip resistance

10m ohm

Probe tip spacing:

Between two outer C tips 7.6 mm

P tip central between two C tips with 3.8 mm spacing

**Probe dimensions:** 

From finger guard to tip 110 mm

Diameter is tapered from 1 4mm nearest the finger guard to 1 mm at tip crown

Will fit Any duplex connect test lead and

extension lead

Safety <30 V only

Spare / optional parts Order part number:

Replacement P needle tip 2003-551 Waffle / serrated P tip 25940-014

#### **HEAVY DUTY KELVIN CLIP**



KC1-C

Kelvin Clip 1 - connect Order part number: 1006-447

## Description

Duplex connect Kelvin Clip 1 is a heavy duty clip for general purpose applications.

Maximum current rating 10 A Connector to probe tip resistance

14m ohm

Clip capacity: 40 mm

Will fit Any duplex connect test lead and

extension lead

Safety <30 V only

## **DLRO** test leads fitted with duplex Connectors

**COMPLETE DUPLEX CONNECT LEAD SETS** 

DLRO test leads

# LARGE TOUCH PROOF INSULATED CLIP – ADJUSTABLE JAW OPENING



KC2-C


Kelvin Clip 2 - connect Order part number: 1006-451

#### Description

Duplex connect Kelvin Clip 2 is a fully insulated touch proof clip for applications where a high safety rating is required.

Maximum current rating

20 A



Connector to clip resistance

10m ohm


Clip capacity: 52 mm to 7 5mm with sliding jaw
Will fit Any duplex connect test lead and

extension lead

Safety CAT IV 600 V

The actual safety CAT rating in use will always be the rating of the lowest part of the complete system For example if used with a DLRO10 without terminal covers the system will be unrated and must not be connected to live voltages above 30 V.

In the example below, using a DLRO10HD a terminal cover should also be used.



## PROBE LEAD-SETS

**AVAILABLE** 

DH1-C



3M Duplex Handspike lead set, with connect (x2)

Order part number: 1006-442

## Description

Two wire, four terminal duplex twist probe lead set 3m long.

## Consists of the following:

DTP1-C Duplex Twist Probe 2 off
TL3-C-BT51 3m lead connect 2 off
Total leadset loop resistance 80m ohm

#### Will fit:

- BT51
- BT51 120V

## DH2-C



6m / 20' version of DH1-C above but only 1 included Order part number: 1006-443

## Description

Single duplex twist probe lead - 6m long.

## Consists of the following:

DTP1-C Duplex Twist Probe 1 off
TL6-C-BT51 6m lead connect 1 off
Total resistance - 1 lead + 1 probe 50m ohm

## Will fit:

- BT51
- BT51 120V

## **DLRO test leads fitted with duplex Connectors**

DLRO test leads

#### DH4-C



Two wire, four terminal duplex probe lead set - 1.5 m One lead fitted with indicator lights.

Order part number: 1006-444

## Description

Two wire, four terminal duplex probe lead set 1.5 m long. One lead fitted with indicator lights.

## Consists of the following:

DP1-C Duplex Probe 2 off
TL1.5-C 1.5 m connect lead 1 off
TL1.5-CL 1.5 m connect lead

LT.5-CL T.5 III CONNECT lead

with indicator lights 1 off

Total leadset loop resistance 48m ohm

## Will fit:

- DLRO10
- DLRO10X
- DLRO10HD



## DH4-CHDC

Order part number: 1006-463

As DH4-C but supplied with DLRO10HD terminal Cover for CATIII  $\,$ 

300 V rating

## DH5-C

Order part number: 1006-445 as DH4-C but 3m long

## **KELVIN CLIP LEAD-SETS**



## KC1-TL3-C

KL1-C Kelvin Clip 3m Lead set - connect (x2)

Order part number: 1006-462

## Description

Two wire, four terminal kelvin clip lead set 3m long.

## Consists of the following:

KC1-C Kelvin clip 2 off TL3-C 3m connect lead 1 off

TL3-CL 3m connect lead

with indicator lights 1 off

Total leadset loop resistance 88m ohm

#### Will fit:

- DLRO10
- DLRO10X
- DLRO10HD

## KC2-TL3-C



KL2-C Insulated Kelvin Clip - Test Lead 3 m connect (x2)

Order part number: 1006-461

## Description

Two wire, four terminal insulated kelvin clip lead set 3m long.

## Consists of the following:

KC2-C Insulated kelvin clip 2 off TL3-C 3 m connect lead 1 off TL3-CL 3 m connect lead

with indicator lights 1 off

Total leadset loop resistance 80m ohm

## Will fit:

- DLRO10
- DLRO10X
- DLRO10HD

ORDERING INFORMATION							
Description Order Code		Description	Order Code				
Duplex connect system		Complete duplex connect lead sets					
Component parts - one of each supplied TL1.5-CL		DH1-C Two wire, four terminal duplex twist					
Connect test leads with indicator light - 1.5 m	1006-456	probe lead set - 3m	1006-442				
TL3-CL Connect test leads with indicator light - 3 m	1006-458	DH2-C Single duplex twist probe lead - 6m	1006-443				
TL6-CL Connect test leads with indicator light - 6 m	1006-459	DH4-C Two wire, four terminal duplex probe lead set - 1 One lead fitted with indicator lights.	.5 m 1006-444				
TL1.5-C Connect test lead without indicator light - 1.5 m	1006-452	DH4-CHDC Two wire, four terminal duplex probe lead set 1.5 m long					
TL3-C Connect test lead without indicator light - 3 m	1006-454	One lead fitted with indicator lights	1006-463				
TL6-C	1000-434	DLRO10HD terminal cover					
Connect test lead without indicator light - 6 m	1006-455	DH5-C					
TL3-C-BT51 Connect test leads for BT51 - 3 m	1007-023	Two wire, four terminal duplex probe lead set - 3 One lead fitted with indicator lights.	m 1006-445				
TL6-C-BT51		Kelvin clip lead-sets					
Connect test leads for BT51 - 6 m	1007-024	Two wire, four terminal kelvin clip lead set - 3 m	1006-462				
EL6-C Connect Extension Lead - 6 m	1006-460	Two wire, four terminal insulated kelvin clip lead set - 3 m	1006-461				
Lead test connection terminations available							
Terminations sold individually							
DP1-C Duplex connect probe	1006-450						
DTP1-C Duplex connect twist probe	1006-449						
CP1-C Concentric duplex connect probe	1006-448						
KC1-C Heavy duty kelvin clip	1006-447						
KC2-C Insulated connect Kelvin clip	1006-451						